



Tel: 01226 761832 or 07801 821791

Email: sales@peakhifi.co.uk

12 Skinpit Lane, Hoylandswaine, Sheffield, S36 7JY


DATE: 12th March 2016

CARTRIDGE/STYLUS INSPECTION REPORT No. A0017

---

<b>CUSTOMER:</b>	Peter Stirling	<b>SERIAL NUMBER:</b>	N/A
<b>MAKE:</b>	Ortofon	<b>SYLUS PROFILE:</b>	Nude Shibata
<b>MODEL:</b>	Cadenza Black	<b>CANTILEVER:</b>	Boron cantilever
<b>CARTRIDGE TYPE:</b>	Moving Coil	<b>MAGNIFICATION:</b>	100 X
<b>MICROSCOPE:</b>	Leica MZ6	<b>CAMERA:</b>	Canon DSLR

---



CONCLUSION

- NOTES:** The customer reported only around 100 hours use but requested an inspection of the stylus as he was concerned he may have damaged the stylus by dropping it rather heavily onto a record.
- CANTILEVER/DAMPING:** The cantilever is in good condition with no signs of damage it is straight and positioned at the correct angle in the cartridge body.
- STYLUS:** The styus is in good condition with no signs of damage. When the oblique lighting technique is used to view the "wear cats eyes" these presented as small round areas consitent with low use as opposed to the larger eliptical areas that indicate a higher degree of wear.
- SUMMARY/  
RECOMMENDATIONS:** The stylus, cantilever and cartridge are all in good condition and typical of a low use cartridge. Recommend checking again at approx 1000 hours use.

SIGNED:

DATED:

12th March 2016